

METHOD FOR HANDLING SLAG POTS OR LADLES AND PYRO-METALLURGICAL TOOLS

[ABSTRACT]

5 Method for handling a slag pot or ladle or pyro-metallurgical
tools comprising the steps of spraying a mineral suspension onto a wall
and putting into service of said slag pot or ladle or of the pyro-
metallurgical tool, wherein said mineral suspension comprises calcium
particles in suspension in an aqueous phase formant a calcium particle
10 slag containing a carbon hydrate at a content between 0.2 and 3%.

[NO DRAWING]