

A B S T R A C T

DEPOLYMERIZATION OF POLYAMIDES

5

Process for the depolymerization of one or more polyamides in the presence of at least a nitrogen-containing compound, the depolymerization taking place at a pressure between 0.5 and 5 atm.

10

As a result a better selectivity towards the monomeric components of polyamides is obtained.

This Sheet Has Been Replaced

