




[Fig. 1]




[Fig. 2]




[Fig. 3]







[Fig. 4]




[Fig. 5]




[Fig. 6]

Combination	Arrangement of marking	Outputs of sensors
1	 Blank Blank	 OFF OFF
2	 Blank M	 OFF ON OFF
3	 M Blank	 ON OFF OFF
4	 M M	 ON OFF ON OFF


[Fig. 7]



[Fig. 8]



(a)



(b)