

TURBINE SHROUD MILLING

ABSTRACT

An exemplary shroud milling method includes milling a convex side of a shroud, milling a concave side of the shroud, and holding a shroud
5 within a common fixture when milling the convex side and when milling the concave side.

Figure 1