




Fig. 1




Fig. 2





Fig. 3

446  1 EMPLOYEE WAS REMOVING TRASH FROM THE DOCK BY BAY NUMBER 5.
2 AS HE WAS REMOVING THE TRASH A FORKLIFT DRIVER WAS EXITING THE TRAILER ON THE FORKLIFT AFTER LOADING BOXES.
3 THE FORKLIFT TIRE GRAZED THE EMPLOYEE'S FOOT AT THIS TIME.
4 THE EMPLOYEE WAS TAKEN TO PRIME MEDICAL AND WAS DIAGNOSED WITH A FOOT CONTUSION.
5 INVESTIGATION IS ONGOING TO VALIDATE EMPLOYEE STATEMENT.

HUMAN ~ 448-1
MEANS OF CONTACT ~ 450
MOBILE EQUIPMENT ~ 448-2

Fig. 4

5/6

**Fig. 5**




Fig. 6