FIGURE 1 – Nitration peak heights measured during Worked Example 2




Figure 2 – Oxidation peak heights measured during Worked Example 2




Figure 3 – Kinematic viscosity at 100°C measured during Worked Example 2




Figure 4 – Coefficient of friction tests by High Frequency Reciprocating Rig (HFRR)




Figure 5 – Coefficient of friction tests by TE-77




Figure 6 – Wear Scar volume tests by MTM-R




Figure 7 – Wear Scar volume tests by High Frequency Reciprocating Rig (HFRR)

