

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

TRANSPARENT ELECTRODE THICKNESS (nm)	20	35	50	60	70	100
VISUAL INSPECTION (INTERFERENCE FRINGE (RAINBOW-LIKE MOIRE))	G	G	G	G	P	P
VISUAL INSPECTION (LIGHTING DEFICIENCY (ALIGNMENT DEFICIENCY))	P	G	G	G	G	G