














Fig. 5




Fig. 6




Fig. 7




Fig. 8






Fig. 10

PLATE SPRING IS IN NORMAL STATE




Fig. 11




Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17