

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9

REPLACEMENT STATE INFORMATION	CONSECUTIVE DEFECT INFORMATION
0	0 0
1	0 0
0	0 1
0	1 0
1	0 1
1	1 0

FIG. 10A




FIG. 10B




FIG. 11A




FIG. 11B




FIG. 11C




FIG. 12

