




FIG 1A




FIG 1B




FIG 2




FIG 3




FIG 4





FIG 5

Continuity in electrical conductor is maintained



Discontinuity of electrical conductor in either extremity





FIG 6




FIG 7




FIG 8




FIG 9




FIG 10




FIG 11