

FIG. 1






FIG. 2**FIG. 3**



FIG. 4*FIG. 5*

FIG. 6

4/6

FIG. 6A

FIG. 6A	FIG. 6B
---------	---------




FIG. 6B




FIG. 7

BUILDING NAME

*** BUILDING

CUSTOMER NUMBER

12-345

TARGET ELEVATOR

NO. 2

TODAY'S WORK PLAN

WORK 1

WORK 2

WORK 3

WORK 4

WORK CONTENT OF WORK 1

COLLISION WITH DOOR IN DOOR CLOSING OPERATION DETECTED 20 TIMES ON THIS ELEVATOR.
PLEASE CHANGE TO EXTEND DOOR OPENING TIME.

CURRENT STATUS

DOOR OPENING SPEED: Δ [m/s]

DOOR OPENING TIME: $\blacktriangle$ [Sec]

DOOR CLOSING SPEED: $\diamond$ [m/s]

AFTER CHANGE

DOOR OPENING SPEED: Δ [m/s]

DOOR OPENING TIME: $\blacklozenge$ [Sec]

DOOR CLOSING SPEED: $\diamond$ [m/s]