




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

Fracture at 9848 cycles of stretching




FIG. 8



FIG. 9A




FIG. 9B



FIG. 10



FIG. 11A




FIG. 11B




FIG. 12




FIG. 13A




FIG. 13B




FIG. 14A




FIG. 14B