







FIG. 3

D1
}

<u>COMMUNICATION HISTORY INFORMATION</u>		
RECEPTION DATE AND TIME	ROADSIDE DEVICE IDENTIFICATION INFORMATION	RADIO WAVE INTENSITY
2018/2/1 8:48	ID0005	32
2018/2/1 9:41	ID0001	18
2018/2/1 9:41	ID0002	10
2018/2/1 9:42	ID0001	18

FIG. 4

4/6




FIG. 5

D1

(1) COMMUNICATION HISTORY INFORMATION IN STEP S203

RECEPTION DATE AND TIME	ROADSIDE DEVICE IDENTIFICATION INFORMATION	RADIO WAVE INTENSITY
2018/2/1 8:48	ID0005	32
2018/2/1 9:41	ID0001	18

(2) COMMUNICATION HISTORY INFORMATION IN STEP S209

RECEPTION DATE AND TIME	ROADSIDE DEVICE IDENTIFICATION INFORMATION	RADIO WAVE INTENSITY
2018/2/1 8:48	ID0005	32
2018/2/1 9:41	ID0001	18
2018/2/1 9:41	ID0002	10

(3) COMMUNICATION HISTORY INFORMATION IN STEP S215

RECEPTION DATE AND TIME	ROADSIDE DEVICE IDENTIFICATION INFORMATION	RADIO WAVE INTENSITY
2018/2/1 8:48	ID0005	32
2018/2/1 9:41	ID0001	18
2018/2/1 9:41	ID0002	10
2018/2/1 9:42	ID0001	18

FIG. 6

