



【FIG. 1】




[FIG. 2]


2




[FIG. 3]




【FIG. 4】




【FIG. 5】




[FIG. 6]




【FIG. 7】




[FIG. 8]




【FIG. 9】




[FIG. 10]




[FIG. 11]




[FIG. 12]



[FIG. 13]



[FIG. 14]



【FIG. 15】

20




【FIG. 16】


22




[FIG. 17]



[FIG. 18]



[FIG. 19]



[FIG. 20]

iruri study cafe

iruri.moon.kr/#/member/thermal/history

Study room reservation/status

Access history management

Sales Management

Sales status

Cancellation/refund status

Ticket management

Ticket information

Ticket management

Promotion Management

Pre-registration for season tickets

Customer care

Customer Information

Send text message

Heat detection management

Heat detection status

Heat detection operation status

2021-02-18 - 2021-02-24

View 50 each


Heat detection operation settings

Fail Pass heat detection Administrator confirmation

Q Search

Heat detection date and time	Cell phone	Customer name	Gender	Pass heat detection	fever detection	Mask	Access	Entrance	Seat	Ticket	Store manager
☐ 2021-02-23 16:17	010-9747-4442	Guest	Male	Failure	36.6	X	Access control	Entrance	1person Non-reserved seat(33G)	Same-day ticket (3 hours)	-
☐ 2021-02-23 10:24	010-7547-5063	Guest	Male	Failure	Not measured	-	Access control	Entrance	1person Non-reserved seat(13G)	Termed ticket (28 days)	-
☐ 2021-02-22 13:15	010-2590-2907	Guest	Male	Failure	Not measured	-	Access control	Entrance	1person Non-reserved seat(34G)	Termed ticket (28 days)	-
☐ 2021-02-22 13:11	010-5639-4532	Guest	Male	Failure	Not measured	-	Access control	Entrance	1person Non-reserved seat(22G)	Same-day ticket (5 hours)	-
☐ 2021-02-22 12:47	010-9926-0688	Guest	Male	Failure	Not measured	-	Access control	Entrance	1person Non-reserved seat(50G)	Termed ticket (28 days)	-
☐ 2021-02-22 09:38	010-4033-6654	Guest	Male	Failure	36	X	Access control	Entrance	1person Non-reserved seat(23G)	Same-day ticket (4 hours)	-
☐ 2021-02-22 08:07	010-5344-4057	Guest	Male	Failure	36.1	X	Access control	Entrance	1person Non-reserved seat(17G)	Timed ticket (50 hours)	-
☐ 2021-02-20 20:06	010-8637-1972	Guest	Male	Failure	36.1	X	Access control	Entrance	1person Non-reserved seat(1G)	Timed ticket (50 hours)	-

[FIG. 21]



[FIG. 22]

The screenshot shows a web browser window with the address bar displaying 'iruri.mooin.kr/#/member/info/shop/thirdparty'. The page title is 'iruri study cafe'. The interface is divided into a left sidebar menu and a main configuration area.

Left Sidebar Menu:

- Real-time usage status
- Study room reservation/status
- Access history management
- Sales Management
 - Sales status
 - Cancellation/refund status
- Ticket management
 - Ticket information
 - Ticket management
 - Promotion Management
 - Pre-registration for season tickets
- Customer care
 - Customer Information
 - Send text message
 - Heat detection management
 - Heat detection status

Main Configuration Area:

Operating period

Start date: 2021-01-19 | End date: not determined | Period: Undefined

Check heat detection

☒ Once a day ☐ Whenever enter
※ Study room users are subject to heat detection whenever they enter or exit.

Check wearing mask

☒ Confirmed ☐ Unconfirmed

Heat detection passing limit

Temperature: 37.5 °C / ☒ Mask wearing

Number of heat detection attempts

Maximum failure: 3 number

Heat detection alarm setting

☒ ON ☐ OFF

Store manager notification

☒ ON ☐ OFF
☒ Always notify


Store manager notification contact information

Please enter your mobile phone number: 1811-8517


Entrance control

☒ ON ☐ OFF
※ If set to OFF, users who fail the heat detection screening can also enter.


[FIG. 24]




[FIG. 25]




[FIG. 26]



【FIG. 27】



[FIG. 28]



【FIG. 29】

