

Fig.1




Fig.2




Fig.3





Fig.4


Fig.5


Fig.6


Fig.7

Fig.8





Fig.9

Fig.10

VEHICLE ID	DETECTION TIME INFORMATION	FIRST ENTRY INFORMATION	SECOND ENTRY INFORMATION
1001	2018/5/10 10:29:06.550	1	0
1002	2018/5/10 10:29:24.278	1	0
1003	2018/5/10 10:29:33.014	1	1
⋮	⋮	⋮	⋮


Fig.11


Fig.12

Fig.13




Fig.14




Fig.15





Fig.16


Fig.17


Fig.18


Fig.19


Fig.20

Fig.21





Fig.22

Fig.23