






FIG. 1



산화막: Oxide layer


FIG. 2



정상: Normal

불량: Defective

FIG. 3



x-axis: the level of A_{eff} value

y-axis:

<left> the time for oxide existed in surface of the layer
to be removed

<right> the time for occurring damages in oxide layer
(under layer)

FIG. 4




FIG. 5