






Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5a




Fig. 5b




Fig. 5c




Fig. 6




Fig. 7a




Fig. 7b






Fig. 7c




Tested STC: 28




Closed Mode

Fig. 8a



Tested STC: 14



Ventilation Mode, side
window planes opened at
90 degrees

Fig. 8b