

100 →





FIG. 1

200 →






FIG. 2

300 →




**FIG. 3**

400 →



**FIG. 4**



**FIG. 5**




FIG. 6

700 →




FIG. 7

800 →




FIG. 8

900 →

9/20





FIG. 9

1000 →

1010




10/20

**FIG. 10**

1100 →

11/20

1110



**FIG. 11**

1200 →

12/20




FIG. 12

# 140 workers on the field

Zone violation

12.19pm, 18 Feb 2016 -

User 1 entered the restricted zone with hot work in progress.

12.04pm, 18 Feb 2015 -

User 1 safety status is amber due to CO in the air,



**FIG. 13**

1400 →

14/20




FIG. 14

# 140 workers on the field

12.19pm, 18 Feb 2016 -

12.04pm, 18 Feb 2015 -

User 1 safety status is amber due to CO in the air,



**FIG. 15**

1600 →




FIG. 16



1800 →




FIG. 18

1900 →




FIG. 19

2000 →




FIG. 20