


1/17
FIG.1



2/17
FIG.2






FIG.3



3/17
FIG.4



4/17
FIG.5







FIG.6




5/17
FIG.7



6/17 FIG.8



7/17
FIG.9



8/17
FIG.10




FIG.11




FIG.12





FIG.13



10/17
FIG.14





FIG.15



12/17
FIG.16





FIG.17

HISTORICAL INFORMATION




150


DATE/TIME	ROOM TEMPERATURE	WINDOW TEMPERATURE	OUTSIDE TEMPERATURE	...	AIR-CONDITIONING CAPACITY
20XX/X/XX 10:15:30	23°C	28°C	24°C	...	** W
20XX/X/XX 10:16:00	23°C	29°C	25°C		** W
20XX/X/XX 10:16:30	24°C	31°C	25°C		** W
⋮					

13/17
FIG.18



14/17
FIG.19





16/17
FIG.21




FIG.22




FIG.23

