

1/4




FIG.1

2/4

200
↓




FIG.2






Stage	as received	post light soaking 1 sun, 70°C, 69 hrs	post regen (DOE#1)	post regen (DOE#2)	post regen (DOE#3)
					
PL counts	16445	15373	15538	19088	20149

FIG.3







FIG.4