

FIG.1




FIG.2




FIG.3




FIG.4





FIG.5


ROUTE
GUIDANCE
(JAPANESE)
[WIDE AREA]
DISPLAY
EXAMPLE



AT TIME OF GUIDANCE
INFORMATION DISPLAY

AT TIME OF TOUCH
PANEL OPERATION

ROUTE
GUIDANCE
(JAPANESE)
[VICINITY]
DISPLAY
EXAMPLE



AT TIME OF GUIDANCE
INFORMATION DISPLAY

AT TIME OF TOUCH
PANEL OPERATION

TRANSFER-
FACILITY
GUIDANCE
DISPLAY
EXAMPLE




FIG.6




FIG.7

INFORMATION DISPLAYED IN AREA OF SECTION 7b
 DISPLAY CONTENTS AND DISPLAY TIMINGS OF VARIOUS TYPES OF GUIDANCE
 INFORMATION AT TIME OF (NO) TOUCH PANEL OPERATION




FIG.8




FIG.9

NEXT
STOP IS

XX STATION

CAR NO. 1
CURRENT
TIME
22:55

運行情報 TRAIN INFORMATION

路線 Line	区間 Section	方向 Direction	状況 Status	原因 Cause
C 線 C Line	AB駅～CD駅 ABeki-CDeki	上り Upper	運転見合わせ not in operation	人身事故 Personal Accident
E 線 E Line	EF駅～GH駅 EFeki-GHeiki	上り Upper	遅延 Delay	人身事故 Personal Accident

TOUCH PANEL OPERATION IS NOT AVAILABLE
AT THE MOMENT

7f

7g