




FIG. 1A




FIG. 1B

FIG. 1C

2/16




FIG. 1D

200




FIG. 2A

202




FIG. 2B




FIG. 3




FIG. 4




FIG. 5





FIG. 6








FIG. 7B


800 →

802	804	806	808	810
TestSegment ID	Rail Indicator	Pulse Count	UIC Code/Comment	Confidence
999_DF040117_006	L	3066	996 BHC	0.57888943
999_DF040117_006	L	3132	996 BHC	0.714833975
999_DF040117_006	L	3266	996 BHC	0.676444054
999_DF040117_006	L	3332	996 BHC	0.744215548
999_DF040117_006	L	3472	996 BHC	0.880108118

FIG. 8







ਫ
ਫ
ਫ
ਫ
ਫ

Image 29618, Location 2240298




FIG. 12




FIG. 13




FIG. 14