




FIG. 1A




FIG. 1B




FIG. 1C




FIG. 1D




FIG. 1E




FIG. 1F

4/39




FIG. 1G




FIG. 1H




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 3E




FIG. 3F




FIG. 3G




FIG. 3H




FIG. 3I




FIG. 3J




FIG. 3K




FIG. 3L




FIG. 3M




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 4D




FIG. 5A




FIG. 5B




FIG. 5C




FIG. 5D




FIG. 5E




FIG. 5F




FIG. 6




FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D




FIG. 8A







FIG. 8B

Ceramic-coated surface under the lip of the clamp






FIG. 10

Front side of the substrate




FIG. 11




FIG. 12A




FIG. 12B




FIG. 12C

35/39




FIG. 13A




FIG. 13B

36/39



FIG. 13C

37/39




FIG. 14A




FIG. 14B




FIG. 15




FIG. 16A




FIG. 16B