




1

FIG. 2




FIG. 3




FIG. 4




FIG. 5

<DISCONNECTION DETECTION INFORMATION> D1

IDENTIFICATION INFORMATION	DATE AND TIME OF DETECTION	CONTENT OF DETECTION
ID0001	2017/12/01 10 : 00 : 00	DISCONNECTION OF INPUT LINE L1

FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10

