

Figure 1




Figure 2




Figure 3




Figure 4






Figure 5



Cryptosporidium oocyst adsorbed on sand remains unaffected.



Breakage of oocyst after contact with active surface.

Figure 6




Figure 7

