




Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5




Fig. 6




Fig. 7




Fig. 8






Fig. 9




Fig. 10




Fig. 11




Fig. 12





Fig. 13

COMPONENT-MOUNTING SUBSTRATE
ACCORDING TO COMPARATIVE EXAMPLE 1



POOR EMBEDDING PROPERTIES

COMPONENT-MOUNTING
SUBSTRATE ACCORDING TO EXAMPLE 4




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18