




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8

Multiple-item-group ID	Parcel ID	Form information	X-ray image	External appearance image
061212_3	00001	aaa	0001_x.xxx	0001_s.yyy
061212_3	00002	aaa	0002_x.xxx	0002_s.yyy
061212_3	00003	aaa	0003_x.xxx	0003_s.yyy

FIG. 9




FIG. 10

80 Confirmation screen

81 Parcel ID

82 Multiple-item-group ID

83

84

85

86

87

88

89

Identical multiple-item-group ID

Parcel ID	Primary inspection result
23456789	OK
34567890	NG
45678901	OK

OK

NG

Sender information

Address	Name	Telephone No.	Others
---------	------	---------------	--------

Receiver information

Address	Name	Telephone No.	Others
---------	------	---------------	--------

Content information

Article Name	Weight	No. of parcels
--------------	--------	----------------

Form information

FIG. 11

Multiple-item-group ID	Parcel ID	Form information	X-ray image	External appearance image	Single-item determination	Multiple-item determination	Destination of distribution
061212_3	00001	aaa	0001_x.xxx	0001_s.yyy	Normal	Dangerous article	2
061212_3	00002	aaa	0002_x.xxx	0002_s.yyy	Normal	Dangerous article	2
061212_3	00003	aaa	0003_x.xxx	0003_s.yyy	Dangerous article	Dangerous article	2

FIG. 12




FIG. 13