

Fig. 1




Fig. 2




Fig. 3






Fig. 4



STATE IN WHICH OCCURRENCE OF
ELECTRICAL DISCHARGE EVENT TO BE
HANDLED IS SUSPECTED

Fig. 5



IT IS NOT STATE IN WHICH OCCURRENCE OF ELECTRICAL DISCHARGE EVENT TO BE HANDLED IS SUSPECTED.

IT IS NOT STATE IN WHICH OCCURRENCE OF ELECTRICAL DISCHARGE EVENT TO BE HANDLED IS SUSPECTED.
NOISE IS CAUSED BY OPERATION OF DEVICE.

Fig. 6




Fig. 7




Fig. 8




Fig. 9




Fig. 10




Fig. 11




Fig. 12






Fig. 13



(a)



(b)

Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19




Fig. 20




Fig. 21




Fig. 22




Fig. 23




Fig. 24




Fig. 25




Fig. 26




Fig. 27




Fig. 28




Fig. 29




Fig. 30




Fig. 31




Fig. 32




Fig. 33




Fig. 34

