




Figure 1





Figure 2

**Figure 3**




Figure 4

104

210

211

86

208

206

86

104

204

202

203

205

207

209

222

224

214

215

216

218

220

5/12

200

201

221

219

217

MAPS

ALARM INFORMATION

REQUEST NUMBER: 100000531

REQUEST TIMESTAMP: 27/05/2014 14:05:06

CLIENT NAME: CLIENT PTY LTD

CLIENT NUMBER: 101

SUBSCRIPTION NUMBER: 1001

INSTALLATION: LLYDALE

LOCATION: BUILDING 1

SYSTEM: SYS-01

ALARM NUMBER: 562

ALARM DESCRIPTION: Stbd Tunnel Conveyor - Pull Cord Switch - STBD FWD Tripped

ALARM ELEMENT	I/O INDEX	TAG	I/O	ADDRESS	DESCRIPTION	ELECTRICAL DIAGRAMS	HYDRAULIC DIAGRAMS	PNEUMATIC DIAGRAMS	OTHER DOCUMENTATION
1	D10214	21LVHV2	I	201.5	Stbd Tunnel Conveyor - Pull Cord Switch - STBD FWD: healthy	PRESS TO DISPLAY	N/A	N/A	N/A
2	-	-	-	-	-	N/A	N/A	N/A	N/A
3	-	-	-	-	-	N/A	N/A	N/A	N/A
4	-	-	-	-	-	N/A	N/A	N/A	N/A
5	-	-	-	-	-	N/A	N/A	N/A	N/A
6	-	-	-	-	-	N/A	N/A	N/A	N/A
7	-	-	-	-	-	N/A	N/A	N/A	N/A
8	-	-	-	-	-	N/A	N/A	N/A	N/A
9	-	-	-	-	-	N/A	N/A	N/A	N/A
10	-	-	-	-	-	N/A	N/A	N/A	N/A
11	-	-	-	-	-	N/A	N/A	N/A	N/A
12	-	-	-	-	-	N/A	N/A	N/A	N/A
23	-	-	-	-	-	N/A	N/A	N/A	N/A
24	-	-	-	-	-	N/A	N/A	N/A	N/A
25	-	-	-	-	-	N/A	N/A	N/A	N/A

Figure 4A




Figure 4B




Figure 4C

8/12




Figure 4D

9/12




Figure 5





Figure 6

**Figure 7**




Figure 8