





100

FIGURE 1







FIGURE 3



400

FIGURE 4






FIGURE 5



600

FIGURE 6



200
FIGURE 7

Vehicle ID	Status	Faults	Fault Type	Hours in Service	Hours Since Inspection	Hours Since Calibration	Work Order?	Depot Assignment
100	Available	Yes	1A	4	4	4	No	No
100A	On trip	No		5	3	3	No	No
100B	Available	No		2	2	2	No	No

800A

FIGURE 8A

Depot ID	Available Parking Spots	Depot Operators	Shade	Refueling	Cleaning Services	Maintenance Services	Current Bandwidth
280	2	2	Yes	Yes	Yes	Yes	1 Car/Minute
282	1	0	No	No	No	No	N/A

800B

FIGURE 8B

Vehicle ID	Status	Faults	Fault Type	Hours in Service	Hours Since Inspection	Hours Since Calibration	Work Order?	Depot Assignment
100	Depot	Yes	1A	4	4	4	Yes	280
100A	On trip	No		5	3	3	No	No
100B	Available	No		2	2	2	No	No

900A

FIGURE 9A

Depot ID	Available Parking Spots	Depot Operators	Shade	Refueling	Cleaning Services	Maintenance Services	Current Bandwidth
280	1	2	Yes	Yes	Yes	Yes	1 Car/Minute
282	1	0	No	No	No	No	N/A

900B

FIGURE 9B


1100

FIGURE 11