




FIG. 1




FIG. 2




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8

Reception No.	Parcel ID	Sender information	Destination information	Article name	Others	Parcel image	X-ray image
20180728_080102_1	1234567			Food	Canned fish	xxx.xxx	yyy.yyy
20180728_080103_1	2345678			Mechanical component			
20180728_080104_1	3456789			Clothing			
20180728_080105_1	4567890			Electronic equipment			
20180728_080106_1	5678901			Food	Beef (frozen)		

FIG. 9




FIG. 10

Table of data sets with no parcel ID (failure data)

Reception No. (provisional ID)	Sender information	Destination information	Article name	Others	External appearance image

Return

FIG. 11

81 Confirmation screen

82 Parcel ID

83

84

85

86

87 OK

88 NG

Sender information			
Address	Name	Telephone No.	Others

Receiver information			
Address	Name	Telephone No.	Others

Content information		
Article Name	Weight	No. of parcels

Sender information			
Address	Name	Telephone No.	Others

Receiver information			
Address	Name	Telephone No.	Others

Content information		
Article Name	Weight	No. of parcels

Form information

FIG. 12

Reception No.	Parcel ID	Primary inspection result	Primary inspection	Primary inspection processing date/time	Secondary inspection result	Secondary inspection	Secondary inspection processing date/time
20180728_080102_1	1234567	OK	No abnormality	20180728_082133			
20180728_080103_1	2345678	NG	X-ray	20180728_082344	OK	No abnormality	20180728_110100
20180728_080104_1	3456789	NG	EAD confirmation	20180728_082555	OK	No abnormality	20180728_111010
20180728_080105_1	4567890	NG	Dog inspection	20180728_082800	NG	Explosive	20180728_111620
20180728_080106_1	5678901	NG	Application form	20180728_082911	NG	Prohibited article	20180728_112130

FIG. 13




FIG. 14




FIG. 15

Image data	Primary inspection result	Secondary inspection result	Processing status of parcel	Present position of parcel
Absent	—	—	Before 0th-order process	0th-order work site
Present	—	—	Conveyance to primary inspection site	Conveyance path between 0th-order work site and primary inspection site
Present	OK	—	End of inspection	Sorter
Present	NG	—	Conveyance to secondary inspection site	Conveyance path between primary inspection site and secondary inspection site
Present	NG	OK	End of inspection	Sorter
Present	NG	NG	End of inspection	Reject

FIG. 16


100

101 Search item: parcel ID


102 Search key: 12345678

103 1/1

83



84



104 Processing status

105 Present position

85

Sender information

Address	Name	Telephone No.	Others
---------	------	---------------	--------

Receiver information

Address	Name	Telephone No.	Others
---------	------	---------------	--------

Content information

Article Name	Weight	No. of parcels
--------------	--------	----------------

86

Sender information

Address	Name	Telephone No.	Others
---------	------	---------------	--------

Receiver information

Address	Name	Telephone No.	Others
---------	------	---------------	--------

Content information

Article Name	Weight	No. of parcels
--------------	--------	----------------

Form information

FIG. 17

110

111

Search item:

112

Search result table

113

Search

114

Search key:

Parcel ID	Sender information	Destination information	External appearance image	Inspection stage	Inspection result	Present position

Return

FIG. 18