

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

|                       |  |                                |  |                                  |  |                        |  |
|-----------------------|--|--------------------------------|--|----------------------------------|--|------------------------|--|
| AUTOMATION<br>ENABLED |  | INVERTER<br>OPERATED           |  | LOGGED IN                        |  | ABNORMALITY            |  |
| CONTACT<br>DETECTED   |  |                                |  | RISING                           |  |                        |  |
| LARGE                 |  | 1234                           |  | 345.000                          |  | mm                     |  |
| OK                    |  |                                |  |                                  |  | 0mm                    |  |
| SMALL                 |  | SETTING 1234                   |  | LOWERING                         |  | SET                    |  |
| CLOSED<br>MODE        |  | OPEN<br>MODE                   |  | HOLD DOWN                        |  |                        |  |
| MAIN                  |  | SETTING                        |  | AUTOMATIC<br>CONDITION           |  | ALARM                  |  |
| 10/25 16:11           |  | PRODUCT<br>TEMPERATURE 123.0°C |  | ACCUMULATED TIME<br>123456h45min |  | AUTOMATIC<br>OPERATION |  |
|                       |  |                                |  |                                  |  | AUTOMATIC<br>STOP      |  |
|                       |  |                                |  |                                  |  | BUZZER<br>STOP         |  |

FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14

