






Fig. 1 Schematic of the Process

Reference Fingerprint



Incoming Fingerprint



Parameters

Match Mode: 3

Fingerprint Len: 8787

Magnetic Image Length: 4087

Parameters

Match Mode: 3

Fingerprint Len: 12381

Magnetic Image Length: 4247

Event Detail

Transaction Code	980041003424783M9M1JD1KTG7V
Barcode	459415
Internal Device ID	10000001
Authentication Result	SUCCESS
Component A	0.912065
Component B	0.929855
Component C	0.986152
Best Reference	0
Fail Reason	
Transaction Time	2011-04-26 11:19:55.0

Fig 2.1 a: - Measure of affixation by rub resistance test for sample no. 1 from 1st set of Samples




Fig 2.1 b: - Measure of affixation by rub resistance test for sample no. 2 from 1st set of Samples




Fig 2.2: - Laundry test result for sample from 1st set of Samples




Fig 2.3: - Dry Crumpling test result for sample from 1st set of Samples




Fig 2.4: - Wet Crumpling test result for sample from 1st set of Samples




Fig 2.5: - Accelerated ageing test result for sample from 1st set of Samples




Fig 3.1 a: - Measure of affixation by rub resistance test for sample no. 1 from 2nd set of Samples




Fig 3.1 b: - Measure of affixation by rub resistance test for sample no. 2 from 2nd set of Samples




Fig 3.2: - Laundry test result for sample from 2nd set of Samples




Fig 3.3: - Dry Crumpling test result for sample from 2nd set of Samples




Fig 3.4: - Wet Crumpling test result for sample from 2nd set of Samples




Fig 3.5: - Accelerated ageing test result for sample from 2nd set of Samples




Figure 4




Figure 5




Figure 6(a)




Figure 6(b)





Figure 7