

100 →





FIG. 1

200 →




FIG. 2




FIG. 3

400 →




FIG. 4




FIG. 5




FIG. 6

700 →





FIG. 7

800 →



900 →

9/20




FIG. 9

1000 →

1010




FIG. 10

1100 →

11/20

1110




FIG. 11

1200 →

12/20



FIG. 12

140 workers on the field

Zone violation

12.19pm, 18 Feb 2016 -

User 1 entered the restricted zone with hot work in progress.

12.04pm, 18 Feb 2015 -

User 1 safety status is amber due to CO in the air,



FIG. 13

1400 →

14/20




FIG. 14

FIG. 15

1600 →




FIG. 16




FIG. 17

1800 →




FIG. 18

1900 →




FIG. 19

2000 →




FIG. 20