




FIG.1





FIG. 2




FIG.3




FIG.4A




FIG.4B




FIG.5




FIG.6A




FIG. 6B




FIG.7A






FIG. 7B



[810]


	Timbre	Loudness	THD	Noise
Normal	90.6	75.2	0	-96.86
High	90.8	89.3	2/1/1/1/2/1	-97.58

[820]




[830]

FIG.8



HS	Pub	Drive	Pink	Music	Mall	Bus	Busstop	AVG
2MIC	-88.80	-84.45	-70.97	-35.55	-46.27	-89.20	-77.93	-70.45
3MIC	-87.37	-87.40	-87.38	-70.03	-87.39	-87.32	-87.34	-84.89

[910]



HS	Pub	Drive	Pink	Music	Mall	Bus	Busstop	AVG
2MIC	-82.67	-81.16	-64.42	-30.56	-53.61	-69.52	-63.22	-63.59
3MIC	-84.79	-84.73	-84.81	-54.06	-70.06	-74.38	-73.76	-75.23

[920]

FIG.9




FIG.10