




FIG. 1

Work Order Details

Select a work order to see details

FIG. 2

Orders

Show entriesSearch:

Inspection Order	Inspection Criteria	Zone	Interior/Exterior	Upper/Lower	Inspection Status	First Response	Response Date	Response User ID	Anomaly Desc.	Notes
1 N0007	Verify/Valid	18	Interior	Lower	In Queue				Mark	
2 N0008	Verify/Valid	6	Interior	Lower	In Queue				Mark	

Showing 1 to 2 entries

Previous

1

Next

Work Order Details

Details for Work Order: N0007

Zone: 18

Interior/Exterior Location: Interior

Inspection Status: In Queue

Inspection Revision: D

Inspection Criteria:

Response

Save Update

FIG. 3A

Response:

I

>

Not Verifiable

Does Not Exist

Does Exist

FIG. 3B

Orders									
Show 10 entriesSearch:									
Inspection Order		Inspection Criteria	Zone	Interior/Exterior	Upper/Lower	Inspection Status	First Response	Response Date	Response User ID
1 N0007		Verify/Valid	18	Interior	Lower	Completed	Does Exist	XX/XX/XXX	ID:0001
									Notes
									Anomaly Desc.
									Mark


FIG. 3C

The diagram shows a table with 10 columns and 7 rows of data. Callouts point to the following elements:

- 112: Points to the first data row (N1450320483).
- 114: Points to the 'Inspection Order' header column.
- 126: Points to the 'Exterior' and 'Upper' columns.
- 134: Points to the 'Condition Does Not Exist' header column.
- 136: Points to the 'Condition Exists' and 'Condition Does Not Exist' header columns.
- 140: Points to the 'Notes' header column.
- 144: Points to the 'Response Date' header column.
- 146: Points to the 'Response User ID' header column.

Inspection Order			Zone	Condition Exists	Condition Does Not Exist	Could Not Verify	Response User ID	Response Date	Notes
N1450320483	Exterior	Upper	1b	X			ID:0001	XX/XX/XXXX	
N1450320484	Interior	Upper	1b	X			ID:0001	XX/XX/XXXX	
N1450320485	Exterior	Upper	1b		X		ID:0001	XX/XX/XXXX	
N1450320486	Exterior	Lower	1b	X			ID:0001	XX/XX/XXXX	
N1450320487	Interior	Upper	1b			X	ID:0001	XX/XX/XXXX	
N1450320488	Interior	Upper	1b		X		ID:0001	XX/XX/XXXX	
N1450320489	Interior	Upper	1b						

FIG. 4

**FIG. 5**