




FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7

1y Aged HEU Shell γ -Leak, 4.8395E+06/s, 30 cm air




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13